

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
Company	Dennis Ware
OGM	Steve Demczak

Inspection Report

Permit Number:	C0070006 PARTIAL		
Inspection Type:			
Inspection Date:	Wednesday, March 23, 2011		
Start Date/Time:	3/23/2011 10:00:00 AM		
End Date/Time:	3/23/2011 12:00:00 PM		
Last Inspection:	Thursday, February 17, 2011		

Inspector: Steve Demczak,

Weather: <u>Sunny, 30's, Snow Covered.</u> InspectionID Report Number: <u>2692</u>

Types of Operations

Accepted by: jhelfric 4/4/2011

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	8,885.00
Total Disturbed	87.30
Phase I	95.30
Phase II	95.30
Phase III	8.00

Mineral C	wnership
-----------	----------

✓ Federal	✓ Underground
✓ State	Surface
☐ County	☐ Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Stephen J Danuf Steve Demozak,

Date



Inspector ID Number: 39

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 23, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil	~		✓	
4.a	Hydrologic Balance: Diversions	~		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	V		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		~		
8.	Noncoal Waste	~		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	Y		~	
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading	✓		Y	
13.	Revegetation	✓		~	
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 23, 2011

Page 3 of 3

2. Signs and Markers

The identification sign is next to the road to the site. The permittee has removed the subsidence markers from the permit area.

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

The diversions were snow covered.

4.c Hydrologic Balance: Other Sediment Control Measures

The complete site is pocked to prevent sediment from leaving the reclaimed area.

8. Noncoal Waste

The site was clear of non-coal waste. The site is snow covered.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The site is completely backfilled and graded to AOC.

13. Revegetation

The site is snow covered.

16.a Roads: Construction, Maintenance, Surfacing

The County road is snow covered and could not travel to the upper benches.